



03-05.06.2011

**Date** : 03.06.2011

**Time** : 14:00

**Subject** : Bulletin No: 1

**Document No** : 1.3

---

**From** : *The Stewards of the Meeting*

**To** : *All competitors/Crew Members*

*Number of pages 6 Attachments 0*

---

### **1- Secretary of the Stewards (Supplementary Regulations Article 2.5)**

Delete: Ms. Gökçe Özgül

Add: Mr. Serhan Acar

Please note that Ms. Gökçe Özgül is not secretary of the stewards anymore.

### **2- FIA Observers and Delegates (Supplementary Regulations Article 2.6)**

Please note that the Mr. Jerome Toquet has been appointed as FIA Technical Delegate.

FIA Technical Delegate Mr. Jerome Toquet (FRA)

### **3- Service Observers (Judges of Fact) (Supplementary Regulations Article 2.7)**

Delete: Mr. Necip Bektaş & Mr. Galip Bilgin

Add: Mr. Gökhan Elbir & Mr. Ömer Özak

Please note that Mr. Necip Bektaş and Mr. Galip Bilgin are not service observers anymore.

### **4- Road Book Changes**

Please note that, due to change of location of parc ferme and scrutineering areas, following road book pages have been amended as below. Same changes apply for related Rally Guide pages as well.



4.1) Page 18 Trip Meter Calibration

**TRIP MASTER KALIBRASYONU / TRIP MASTER CALIBRATION**

Tripmaster'ınızın kalibre edilmesi için 1,10 kilometrelik bir yol kısmı, aşağıda belirtilmiştir. Bu kısım, etaplardan Servis Alanı'na dönüş yolunda, Yol Notu Sayfa 30 Kutu 25'ten itibaren başlamaktadır.

In order to calibrate your tripmeter, a road part of 1,10 km is indicated below. This proposed part, is on the return way from special stages to Service Park and starts from Road Book Page 30 Box 25 onwards.

Total Distance Toplam Mesafe	Partial Distance Kalan Mesafe	Direction / Yön	Information / Açıklama	Distance to go Kalan Mesafe
0,00	0,00	←	CIP İç Hat Yolcular CIP Domestic Passengers ANADOLU JET TURKISH AIRLINES	1,10
0,22	0,22	←	BUMP	0,88
0,75	0,53	←	BUMP BEKLEMEN YASAKTIR	0,35
1,06	0,31	←	BUMP	0,04
1,10	0,04	←	TRAFO 6 TRAFO ODASI	0,00

www.bosphorusrally.com


4.2) Page 20 General Layout




4.3) Page 1-58 Service Out / Parc Ferme In



4.4) Page 2-4 Parc Ferme Out / Service In



4.5) Page 2-58 Service In / Service Out




4.6) Page 2-60 Service In / Service Out / Parc Ferme In



4.7) Page 3-40 Regrouping Out / Service In



4.8) Page 3-42 Service In / Service Out



4.9) Page 3-42 Service In / Service Out / Finish Podium



5- Light Fitting Zone in Regrouping (TC2A)

- On Friday (03 June) evening, a zone will be established, under the supervision of scrutineers, where a member of the team may fit additional driving lights to their competing vehicle. The location of the zone will be inside the Regrouping Area, prior to SS3 - Airport.
  - ONLY additional lights and associated mounting brackets or "pods" plus connections may be deposited within the zone by a team person up to 15 minutes prior to the arrival of any of the team's vehicles.
  - ONLY one team member per car may remain inside the zone to assist in the fitting of the lights.
- Crews, who do not wish to fit additional driving lights, may drive through the light fitting zone without stopping.
- Additional lights may be transported to this zone other than in the competing car.

Mr. Claude Maccario  
 Chairman

Mr. Tomas Kunc

Ms. Banu Başeren

FIA Stewards of the Meeting